Oil Field Environmental Incident Summary

Responsible Party: Petro Harvester Operating Company, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: KUROKI MADISON UNIT

Field Name: KUROKI Well File #:

Date Incident:12/5/2014Time Incident:08:00Facility ID Number:401172-01County:BOTTINEAUTwp:163Rng:81Sec:12Qtr:NE NW

Location Description: Kuroki - Midale Unit CTB

Submitted By: Gary Watson Received By:

Contact Person: Galen Kalmbach

5160 TENNYSON PARKWAY

SUITE 3000 E PLANO, TX 75024

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Units

Type of Incident: Vessel Leak

Spilled

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Recovered Units

Followup

Units

Oil	20	Barrels	20	Barrels	
Brine	225	Barrels	225	Barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Minimal impact to facility site soil.

Areal Extent:

Potential Environmental Impacts:

Minimal impact to facility site soil.

Action Taken or Planned:

Released fluids will be vacuumed up, fly ash will be applied to the affected facility soil, collected and disposed at an approved disposal facility.

Wastes Disposal Location: Approved disposal facility.

Agencies Involved:

Updates

Date: 12/5/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a vessel leak, remained on location within the diking according to the report. NDIC retains oversight.